

LinHES - Bug # 515: firmware missing for HVR-1600 card

| | | | |
|---------------------|--|------------------|------------|
| Status: | Closed | Priority: | Normal |
| Author: | lucidblue | Category: | |
| Created: | 08/19/2009 | Assignee: | cecil |
| Updated: | 03/20/2010 | Due date: | 12/31/1969 |
| Description: | <p>In the default install the cx18 driver seems to load but it complains that it cannot find the firmware. After copying the 3 firmware files into /lib/firmware everything worked fine and seems to work correctly.</p> <p>the 3 files: v4l-cx23418-apu.fw v4l-cx23418-cpu.fw v4l-cx23418-dig.fw</p> <p>Link to download for downloading: http://dl.ivtvdriver.org/ivtv/firmware/cx18-firmware.tar.gz</p> <p>Info found at: http://www.mythtv.org/wiki/Hauppage_HVR-1600</p> <p>Thanks, LB</p> | | |

History
